

TS-75M-1-31200 LOWER,HINO KC-FC3JDBA

PX1000685-01 MOUNTING PARTS

PY1000899-00 OPTIONS

ASSEMBLY

CLICK HERE TO **DOWNLOAD** THE COMPLETE MANUAL

- Thank you very much for reading the preview of the manual.
- You can download the complete manual from: www.heydownloads.com by clicking the link below



- Please note: If there is no response to CLICKING the link, please download this PDF first and then click on it.

CLICK HERE TO **DOWNLOAD** THE COMPLETE MANUAL

TS-75M-1-31200 LOWER,HINO KC-FC3JDBA

Pos No.	Parts No	Parts Name	Qty	Unit	Technical Data	Serial No (Start)	Serial No (End)	Remark
1	36302220000	SHAFT,PROPELLER (PUMP)	1					
2	90101508020	BOLT	8		M8X20			
3	90302040801	WASHER,SPRING	8		8			
11	36300110010	COUPLING	1					
12	36302220010	PIPE	1					
13	36300110020	COUPLING	1					
21	36300115010	JOINT KIT	2					
34	82456101000	NIPPLE,GREASE	1		A-PT1/8			

TS-75M-1-31200 LOWER,HINO KC-FC3JDBA

Pos No.	Parts No	Parts Name	Qty	Unit	Technical Data	Serial No (Start)	Serial No (End)	Remarks	Pages
2	32860192000	SUPPORT	1						
3	37000168650	PIN	1						
4	53617035000	PIN,SNAP	1						
5	37000108100	PIN	1						
6	80136340028	PIN,SPLIT	2		4X28				

TS-75M-1-31200 LOWER,HINO KC-FC3JDBA

Pos No.	Parts No	Parts Name	Qty	Unit	Technical Data	Serial No (Start)	Serial No (End)	Remarks	Page
1	82100002353	RELAY	1						
2	82100000952	GROMMET	1				368045		
	82100000920	GROMMET	1			368046			
3	32800024000	HARNESS	1			368046	368073		
	32800021000	HARNESS	1				368045		
4	32800022001	HARNESS	1				368045		
	32800023000	HARNESS	1			368046			
5	91810130240	FASTENER	20						
6	90101206020	BOLT	2		M6X20		368045		
7	90302040601	WASHER,SPRING	2		6		368045		
8	90201200600	NUT	2		M6		368045		
9	90303070601	WASHER,PLAIN	4		6		368045		
10	37000566430	SUPPORT	1				368045		
12	82100000191	TERMINAL	1			368046	368073		
13	82100000183	INSULATOR	1			368046	368073		
14	82100000192	TERMINAL	1			368046	368073		
15	82100000182	INSULATOR	1			368046	368073		
16	91810130270	FASTENER	1			368046			
17	32800025000	HARNESS	1			368074			
18	82115001002	CONNECTOR	2			368074			
27	82100000793	FUSE	1		30A,6.5X30				
28	82100000688	HOLDER,FUSE	1						
30	82100002354	CONNECTOR ASSY	1						

TS-75M-1-31200 LOWER,HINO KC-FC3JDBA

Pos No.	Parts No	Parts Name	Qty	Unit	Technical Data	Serial No (Start)	Serial No (End)	Remarks	Pages
1	32770940010	COVER	1						
2	32770940020	COVER	1						
3	32770940030	SUPPORT	1						
4	32690000040	SUPPORT	1						
5	32770940040	SUPPORT	1						
7	32690000070	SUPPORT	1						
9	32690040050	COVER	1						
10	32690040060	COVER	1						
14	90101210022	BOLT	22		M10X22				
17	90201201000	NUT	5		M10				
18	90302041001	WASHER,SPRING	22		10				
19	90303071001	WASHER,PLAIN	15		10				
20	32772330700	SUPPORT	1						

TS-75M-1-31200 LOWER,HINO KC-FC3JDBA

Pos No.	Parts No	Parts Name	Qty	Unit	Technical Data	Serial No (Start)	Serial No (End)	Remarks	Pages
1	32763871001	SUPPORT (RIGHT)	1						
2	32763872001	SUPPORT (LEFT)	1						
3	32763873001	SPACER (FRONT)	2						
4	32763874001	SPACER (REAR)	2						
5	37000554890	PLATE	4						
6	32763875000	SUPPORT	4						
7	32763876000	PLATE	4						
8	37000512680	PLATE	1						
9	32763870010	U-BOLT	2						
10	90201201600	NUT	4		M16				
11	32763823000	SUPPORT	2						
14	32763826000	SUPPORT	1						
15	82100002041	CLAMP	1						
16	90101208012	BOLT	1		M8X12				
17	90302040801	WASHER,SPRING	1		8				

CLICK HERE TO **DOWNLOAD** THE COMPLETE MANUAL

- Thank you very much for reading the preview of the manual.
- You can download the complete manual from: www.heydownloads.com by clicking the link below



- Please note: If there is no response to CLICKING the link, please download this PDF first and then click on it.

CLICK HERE TO **DOWNLOAD** THE COMPLETE MANUAL